

April 24, 2014

Ms. Erin Brower  
New York City School Construction Authority  
Industrial and Environmental Hygiene  
30-30 Thomson Avenue  
Long Island City, NY 11101

**RE: Public School 63M**  
**121 East 3<sup>rd</sup> Street, New York, New York**  
**Project #: M063-46481 LLW#: 078063**

Dear Ms. Brower,

Asbestos abatement work was performed at the above referenced school on April 23, 2014. Abtron Associates Inc. was the abatement contractor and Taylor Environmental Group, Inc. performed the air monitoring and project monitoring during the abatement work. The following chart indicates work area location, amount and type of ACM and method of abatement.

Work Area	Type of ACM	Amount of ACM	Abatement Method
Exterior Façade –East Elevation	Red Paint On Façade	18 Square Feet	Exterior Vertical Surface (Scaffold Construction)

In addition, a visual inspection of the above referenced location was conducted by a Taylor Environmental Group, Inc. Project Monitor in accordance with New York City Title 15, New York State Industrial Code Rule #56, AHERA and all other applicable federal, state and local regulations. Air clearance for reoccupancy was achieved in the above referenced location on April 23, 2014. Based upon the final visual inspection and the sample results, the above referenced location has met re-occupancy criteria as defined in all applicable federal, state and local regulations.

If you have any questions, or require further information, please contact me at our Floral Park office.

Sincerely,



Chris McElgun  
Project Manager

Cc: W. Hernandez – C/Engineer  
D. Cameron – Principal (PS 63M)  
D. Spielberg – Principal (TNS)  
C. Dumitrescu – SCA PO  
M. Joseph – (TNS)

