

June 6, 2014

Ms. Erin Brower
 New York City School Construction Authority
 Industrial and Environmental Hygiene
 30-30 Thomson Avenue
 Long Island City, NY 11101

RE: Public School 63M
121 East 3rd Street, New York, New York
Project #: M063-46481 LLW#: 078063

Dear Ms. Brower,

Asbestos abatement work was performed at the above referenced school on June 6, 2014. Abtron Associates Inc. was the abatement contractor and Taylor Environmental Group, Inc. performed the air monitoring and project monitoring during the abatement work. The following chart indicates work area location, amount and type of ACM and method of abatement.

Work Area	Type of ACM	Amount of ACM	Abatement Method
Exterior Façade – 3 rd Floor Elevation 1	Red Paint On Façade	923 Square Feet	Exterior Vertical Surface (1 st Application)
Exterior Façade – 3 rd Floor Elevation 1	Red Paint On Façade	6630 Square Feet	Exterior Vertical Surface (Removal)

In addition, a visual inspection of the above referenced locations was conducted by a Taylor Environmental Group, Inc. Project Monitor in accordance with New York City Title 15, New York State Industrial Code Rule #56, AHERA and all other applicable federal, state and local regulations. Air clearance for reoccupancy was achieved in the above referenced locations on June 5, 2014. Based upon the final visual inspection and the sample results, the above referenced locations have met re-occupancy criteria as defined in all applicable federal, state and local regulations.

If you have any questions, or require further information, please contact me at our Floral Park office.

Sincerely,



Chris McElgun
 Project Manager

Cc: W. Hernandez – C/Engineer
 D. Cameron – Principal (PS 63M)
 D. Spielberg – Principal (TNS)
 C. Dumitrescu – SCA PO
 M. Joseph – (TNS)

